MIDALLOY ERNI-CI (FM99) BARE WIRE

CLASSIFICATION

AWS 5.15 Class ERNi-CI / ASME SFA 5.15 Class ERNi-CI

DESCRIPTION

• MIDALLOY ERNi-CI nickel alloy bare wire is used for GMAW and GTAW welding.

APPLICATIONS

- MIDALLOY ERNi-CI nickel alloy bare wire is used for Mig and Tig joining of various cast irons.
- This alloy can also be used for overlay, build-up, and repair, where easily machinable welds are required.
- This alloy can also be used for dissimilar-welding for applications such as cast irons to low-alloy or carbon steels.
- A preheat and inter-pass temperature of 350°F minimum is recommended during welding.

TYPICAL CHEMISTRY

С	Mn	Si	Fe	Ni + Co
.01	.25	.05	.25	99.2
Р	S	Мо	Cu	Mg
.001	.002	.02	.13	.01

TYPICAL MECHANICAL PROPERTIES

TENSILE STRENGTH	70,000 PSI
YIELD STRENGTH	36,000 PSI
ELONGATION	40%

RECOMMENDED WELDING PARAMETERS

(See attached)

STANDARD PACKAGING

TIG 10 lb. tube / 60 lb. carton

• MIG 30 lb. spool

10-15-2010

The contents of this publication are presented for informational purposes only, and while every effort has been made to ensure their accuracy, they are not to be construed as warranties or guarantees, express or implied, regarding the products or services described herein or their use or applicability. We reserve the right to modify or improve the designs or specifications of such products at any time without notice.



TYPICAL WELDING PARAMETERS FOR NICKEL ALLOYS

GMAW (SHORT CIRCUITING MODE)

WIRE DIA.	AMPERAGE	VOLTAGE	WIRE SPEED, IN./MIN.	JOINT THICKNESS IN.	GAS
	70-90	18-20	150-200	.050-3/16	75Ar/25He
.035"	70-90	17-20	150-200	.050-3/16	90He/7.5Ar/2.5Co2
	70-90	17-20	150-200	.050-3/16	69Ar/30He/1Co2
	75-160	19-22	175-225	1/8-3/4	75Ar/25He
.045"	75-160	19-22	175-225	1/8-3/4	90He/7.5Ar/2.5Co2
	75-160	18-22	175-225	1/8-3/4	69Ar/30He/1Co2

GMAW (SPRAY TRANSFER MODE)

<u> </u>						
.045"	190-250	30-32	300-350	3/8 and UP	100Ar	

GMAW (PULSED CURRENT MODE)

.045	120-150	18-20	175-225	1/8-3/4	75Ar/25He
pea	k 250-300				
	120-150	18-20	175-225	1/8-3/4	69Ar/30He/1Co2
pea	k 250-300				

GTAW (TIG)

<u>a </u>					
JOINT THICKNESS IN.	TUNGSTEN ELECTRODE DIA. IN.	FILLER WIRE DIA. IN.	AMPERAGE	VOLTAGE	GAS
.030 to 1/16	1/16	1/16	35-60	9-12	100Ar
1/16 to 1/8	1/16 to 3/32	1/16 or 3/32	50-95	9-12	100Ar
1/8 to 1/4	3/32 or 1/8	3/32 or 1/8	75-150	10-13	100Ar
1/4 and up	3/32 or 1/8	3/32 or 1/8	95-200	10-13	100Ar

SAW (SUBMERGED ARC)

5, tit (5521112116122 ; tit			
WIRE DIA.	AMPERAGE	VOLTAGE	
3/32"	275-350	28-30	Suitable flux
1/8"	350-450	29-32	Suitable flux

SMAW (COATED ELECTRODES)

DIA. & LENGTH	AMPERAGE/FLAT	AMPERAGE/ VERT. & OVERHEAD	VOLTAGE
3/32" x 12"	70-85	65-75	24-28
1/8" x 14"	85-110	80-90	26-30
5/32" x 14"	110-140	100-120	28-32
3/16" x14"	120-160	110-130	28-32

The contents of this publication are presented for informational purposes only, and while every effort has been made to ensure their accuracy, they are not to be construed as warranties or guarantees, express or implied, regarding the products or services described herein or their use or applicability. We reserve the right to modify or improve the designs or specifications of such products at any time without notice.

